

## P158

**STAMPING** P 158 1960

**USGS QUAD MAP** MADISON JUNCTION (1986)

**NGS PID** PY0089

**LATITUDE** 44.651111

**LONGITUDE** -110.821389

**ELEVATION** 2102 m

---

**DATE OF DESCRIPTION** 2003

**DESCRIPTION** Proceed 11.35 mi southwest along the Madison-Norris highway from the junction at Norris (alternatively, 2.0 mi northeast from the junction at Madison). Bench mark is 0.4 mi northeast of the Tuff Cliff exhibit panel and parking area, 102 yards southwest of a corrugated culvert and stone headwall, 44 ft southeast of the centerline of the highway, 21 feet east of the east edge of a dirt parking area, 20 ft northeast of a shallow draw draining southeast to the Gibbon River, about 3 ft below the highway, and in the top of a concrete post projecting 4 inches.

In 2003 the bench mark was searched for and not found, presumed destroyed. A square indentation in the ground is present where the NGS description says the concrete post should be; therefore, it seems likely that the post and bench mark have been removed.



Square indentation where concrete post into which the bench mark was set probably used to be located.